



TECHNICAL REPORT REMR-CO-4

STABILITY OF DOLOS AND TRIBAR OVERLAYS FOR REHABILITATION OF STONE-ARMORED RUBBLE-MOUND BREAKWATER AND JETTY TRUNKS SUBJECTED TO BREAKING WAVES

lò


Robert D. Carver, Brenda J. Wright Coastal Engineering Research Center

DEPARTMENT OF THE ARMY Waterways Experiment Station, Corps of Engineers PO Box 631, Vicksburg, Mississippi 39180-0631



February 1988 Final Report

Approved For Bublic Belesse, Distriction and Unimited



US Army Corps of Engineers
Washington, DC 20314-1000

The following two letters used as part of the number designating technical reports of research published under the Repair Evaluation, Maintenance, and Rehabilitation (REMR) Research Program identify the problem area under which the report was prepared:

	Problem Area		Problem Area		
	Concrete and Steel Structures	EM	Electrical and Mechanical		
GT		Ė	Environmental Impacts		
HY		ΘM	Operations Management		
00	Chaetal				

Destroy this report when no longer needed. Do not return it to the originator.

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.

COVER PHOTOS

TOP — Field Research Facility, Duck, North Carolina.

BOTTOM — Testing of a repair option for the San Pedro Breakwater.



Unclassified
SECURITY CLASSIFICATION OF THIS PAGE

1a. REPORT SECURITY CLASSIFICATION 1b. RESTRICTIVE MARKINGS 2a. SECURITY CLASSIFICATION AUTHORITY 2b. DECLASSIFICATION AUTHORITY 2b. DECLASSIFICATION AUTHORITY 2c. Available for public release; dunlimited. 2c. MONITORING ORGANIZATION REPORT NUMBER(S) 5c. MONITORING ORGANIZATION REPORT NUMBER(S) 7a. NAME OF PERFORMING ORGANIZATION 2c. Available for public release; dunlimited. 2c. MONITORING ORGANIZATION REPORT NUMBER(S) 7a. NAME OF PERFORMING ORGANIZATION 2c. Available for public release; dunlimited. 2c. Available for publi	Form Approved OMB No. 0704-0188 Exp. Date: Jun 30, 1986			
28. SECURITY CLASSIFICATION AUTHORITY 28. DECLASSIFICATION/DOWNGRADING SCHEDULE 4. PERFORMING ORGANIZATION REPORT NUMBER(S) Technical Report REMR-CO-4 63. NAME OF PERFORMING ORGANIZATION REPORT NUMBER(S) TECHNICAL REPORT REMR-CO-4 64. NAME OF PERFORMING ORGANIZATION (ff applicable) Research Center 66. ADDRESS (Gry, State, and ZIP Code) PD Box 631 Vicksburg, MS 39180-0631 83. NAME OF FUNDING/SPONSORING ORGANIZATION (ff applicable) US Army Corps of Engineers 86. ADDRESS (Gry, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 133. TYPE OF REPORT 135. TYPE OF REPORT 151. TIBLE (Include Security Classification) See reverse. 17. COSATI CODES FIELD GROUP SUB-GROUP An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value				
unlimited. 4. PERFORMING ORGANIZATION REPORT NUMBER(S) Technical Report REMR-CO-4 5. MONITORING ORGANIZATION REPORT NUMBER(S) Technical Report REMR-CO-4 6a. NAME OF PERFORMING ORGANIZATION USAEWES, Coastal Engineering Research Center 6c. ADDRESS (Gry, State, and ZIP Code) PO Box 631 Vicksburg, MS 39180-0631 8a. NAME OF FUNDING (SPONSORING ORGANIZATION US Army Corps of Engineers 8c. ADDRESS (Gry, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report Final report Final report FROM 13b. TIME COVERED FROM TO 14 DATE OF REPORT (Year, Month, Day) 15. PAGE OF February 1988 17. COSATI CODES FIELD GROUP An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value				
Technical Report REMR-CO-4 6a. NAME OF PERFORMING ORGANIZATION USAEWES, Coastal Engineering Research Center 6c. ADDRESS (City, State, and ZIP Code) PO Box 631 Vicksburg, MS 39180-0631 8a. NAME OF FUNDING/SPONSORING ORGANIZATION US Army Corps of Engineers 8c. ADDRESS (City, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report FROM To February 1988 16. OFFICE SYMBOL (If applicable) WESCW 7b. ADDRESS (City, State, and ZIP Code) PROGRAM PROJECT TASK NO. NO. TASK NO. 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT FROM TO February 1988 16. SUBPLEMENTARY NOTATION See reverse. 17. COSATI CODES Armor units Jetties Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value	Available for public release; distribution			
65. NAME OF PERFORMING ORGANIZATION USAEWES, Coastal Engineering Research Center 66. OFFICE SYMBOL (If applicable) WESCW 76. ADDRESS (City, State, and ZIP Code) PO Box 631 Vicksburg, MS 39180-0631 88. NAME OF FUNDING/SPONSORING ORGANIZATION US Army Corps of Engineers 86. ADDRESS (City, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final Teport Final Teport Final Teport Final Teport 15. COSATI CODES FIELD GROUP An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value	-			
USAEWES, Coastal Engineering Research Center 6c. ADDRESS (Gry, State, and ZIP Code) PO Box 631 Vicksburg, MS 39180-0631 8a. NAME OF FUNDING/SPONSORING ORGANIZATION USATTUP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT SIB TIME COVERED FORM TO February 1988 16. SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES Armor units Field GROUP SUB-GROUP Armor units Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewards and stability occurring at the lower value and sta				
PO Box 631 Vicksburg, MS 39180-0631 8a. NAME OF FUNDING/SPONSORING ORGANIZATION US Army Corps of Engineers 8c. ADDRESS (City, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(5) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report 15. SUBJECT TERMS (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value				
### Vicksburg, MS 39180-0631 ### Sa. NAME OF FUNDING/SPONSORING ORGANIZATION US Army Corps of Engineers ### Bb. OFFICE SYMBOL (If applicable) ### Mashington, DC 20314-1000 ### PROJECT TASK NO. NO. NO. IT. TASK NO. NO. IT. TASK NO. IT. TASK NO. IT. TITLE (Include Security Classification) ### Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves ### 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. ### 13a. TYPE OF REPORT Final report FROM TO February 1988 ### 15. SUBJECT TERMS (Continue on reverse if necessary and identify by block Armor units Jetties Breakwaters Rubble-mound) ### 19. ABSTRACT (Continue on reverse if necessary and identify by block Armor units Breakwaters Rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: ### a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. ### Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value in the provided in the stability occurring at the lower value in the provided in the stability occurring at the lower value in the provided in the provided in the stability occurring at the lower value in the provided in the province provided in the province provided in the provided in the provided in the province provid				
ORGANIZATION US Army Corps of Engineers 8c. ADDRESS (City, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report FROM TO 14. DATE OF REPORT (Year, Month, Day) February 1988 15. PAGE OF SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES FIELD GROUP SUB-GROUP Armor units Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value				
8c. ADDRESS (City, State, and ZIP Code) Washington, DC 20314-1000 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report FROM TO February 1988 16. SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES 18. SUBJECT TERMS (Continue on reverse if necessary and identify by block Armor units Jetties Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value	MBER			
Washington, DC 20314-1000 PROGRAM ELEMENT NO. PROJECT NO. TASK NO. 11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report FROM TO February 1988 16. SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES 18. SUBJECT TERMS (Continue on reverse if necessary and identify by block Armor units Jetties Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value				
11. TITLE (Include Security Classification) Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report Fand TO February 1988 16. SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES FIELD GROUP SUB-GROUP Armor units Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value	WORK UNIT			
Stability of Dolos and Tribar Overlays for Rehabilitation of Stone-Armored Rubb Breakwater and Jetty Trunks Subjected to Breaking Waves 12. PERSONAL AUTHOR(S) Carver, Robert D.; Wright, Brenda J. 13a. TYPE OF REPORT Final report To To February 1988 16. SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES TIS. SUBJECT TERMS (Continue on reverse if necessary and identify by block Armor units Jetties Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value	ACCESSION NO. 32325			
13a. TYPE OF REPORT Final report 13b. TIME COVERED FORM TO February 1988 15. PAGE OF Final report 16. SUPPLEMENTARY NOTATION See reverse. 17. COSATI CODES 18. SUBJECT TERMS (Continue on reverse if necessary and identify by block Armor units Jetties Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and rewave height (H/d) with minimum stability occurring at the lower value	le-Mound			
See reverse. 17. COSATI CODES 18. SUBJECT TERMS (Continue on reverse if necessary and identify by block Armor units Jetties Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value	OUNT 35			
17. COSATI CODES FIELD GROUP SUB-GROUP Armor units Jetties				
PIELD GROUP SUB-GROUP Armor units Breakwaters Rubble-mound 19. ABSTRACT (Continue on reverse if necessary and identify by block number) An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value				
An experimental model investigation was conducted to obtain design guida dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: _a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. _b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value	number)			
dolos and tribar overlays used to rehabilitate stone-armored rubble-mound break jetty trunks subjected to breaking waves. It was concluded that: _a. Randomly placed dolos are an acceptable option, provided that a stabi coefficient of 12 is used to size the units. _b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value				
coefficient of 12 is used to size the units. b. Dolos stability proved to be sensitive to relative depth (d/L) and re wave height (H/d) with minimum stability occurring at the lower value				
wave height (H/d) with minimum stability occurring at the lower value	lity			
	s of d/L			
c. Randomly placed tribars are not recommended at slopes steeper than IV however, they may be used at milder slopes with a stability coefficient				
	(Continued)			
20. DISTRIBUTION/AVAILABILITY OF ABSTRACT SUNCLASSIFIED/UNLIMITED SAME AS RPT. DTIC USERS 21. ABSTRACT SECURITY CLASSIFICATION Unclassified				
22a. NAME OF RESPONSIBLE INDIVIDUAL 22b. TELEPHONE (Include Area Code) 22c. OFFICE SYI	MBOL			
DD FORM 1473, 84 MAR 83 APR edition may be used until exhausted. SECURITY CLASSIFICATION O	F THIS PAGE			

16. SUPPLEMENTARY NOTATION (Continued).

A report of the coastal problem area of the Repair, Evaluation, Maintenance, Rehabilitation (REMR) Research Program is available from National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.

19. ABSTRACT (Continued).

- d. Uniformly placed tribars are an acceptable option for a lV-on-1.5H slope, provided they are used in concert with toe buttressing stone, size selection is based on a stability coefficient of 7, and placement of the units replicates that used in the model.
- $\underline{e}.$ Tribar stability appears to be insensitive to \mbox{d}/\mbox{L} and \mbox{H}/\mbox{d} for both types of placement.

PREFACE

Authority to carry out this investigation was granted the US Army Engineer Waterways Experiment Station's (WES) Coastal Engineering Research Center (CERC) by the Headquarters, US Army Corps of Engineers (HQUSACE), under the Repair, Evaluation, Maintenance, and Rehabilitation (REMR) Research Program Work Unit No. 32325, "Use of Dissimilar Armor for Repair and Rehabilitation of Rubble-Mound Coastal Structures."

Tests of dolos and tribar overlays for existing armor stone, which fulfill one milestone of this work unit, were conducted under the general direction of Mr. James E. Crews, and Dr. Tony C. Liu, REMR Overview Committee, HQUSACE; Messrs. Jesse A. Pfeiffer, Jr., Directorate of Research and Development, HQUSACE; John W. Lockhart, Coastal Technical Monitor, HQUSACE; and William F. McCleese, REMR Program Manager, WES, and D. D. Davidson, REMR Coastal Problem Area Leader.

The study was conducted by personnel of CERC under the general direction of Dr. James R. Houston, Chief, CERC, Mr. Charles C. Calhoun, Jr., Assistant Chief, CERC, Mr. C. E. Chatham, Chief, Wave Dynamics Division, and Mr. Davidson, former Chief, Wave Research Branch. Tests were planned by Mr. R. D. Carver, Principal Investigator, and Ms. B. J. Wright, Civil Engineering Technician, both of the Wave Research Branch, CERC. The model was operated by Ms. Wright, assisted by Mr. Frank James, Engineering Technician, and Mr. Greg Gastrell, Engineering Aid, under the supervision of Mr. Carver. This report was prepared by Mr. Carver and Ms. Wright.

Commander and Director of WES at the time of publication of this report was COL Dwayne G. Lee, CE. Technical Director was Dr. Robert W. Whalin.

CONTENTS

		Page
PREFACE		1
CONVERSION FACTORS, NON-SI TO SI (METRIC) UNITS OF MEASUREMENT		3
PART I: INTRODUCTION		4
Background Approach Purpose of Study		4 5 5
PART II: TESTS	• • • • • •	6
Stability Scale Effects Test Procedures Test Equipment Selection of Test Conditions		6 6 9 10
PART III: TEST RESULTS		13
Sea-Side Structure Slope = 1V on 2H Sea-Side Structure Slope = 1V on 1.5H		13 13
PART IV: CONCLUSIONS		17
REFERENCES		18
TABLES 1 and 2		
PHOTOS 1-19		
APPENDIX A: NOTATION		A1

CONVERSION FACTORS, NON-SI TO SI (METRIC) UNITS OF MEASUREMENT

Non-SI units of measurement used in this report can be converted to SI (metric) units as follows:

Multiply	Ву	To Obtain		
degrees (angle)	0.01745329	radians		
feet	0.3048	metres		
inches	25.4	millimetres		
pounds (mass)	0.4535924	kilograms		
pounds (mass) per cubic foot	16.01846	kilograms per cubic metre		
square feet	0.09290304	square metres		
tons (mass) per square foot	9,764.856	kilograms per square metre		

STABILITY OF DOLOS AND TRIBAR OVERLAYS FOR REHABILITATION OF STONE-ARMORED RUBBLE-MOUND BREAKWATER AND JETTY TRUNKS SUBJECTED TO BREAKING WAVES

PART I: INTRODUCTION

Background

- 1. The experimental investigation described herein constitutes a portion of a research effort to provide engineering data for the effective and economical rehabilitation of rubble-mound breakwaters and jetties. In this study, a rubble-mound breakwater or jetty is defined as a protective structure constructed with a core of quarry-run stone, sand, or slag and protected from wave action by one or more stone underlayers and a cover layer composed of selected quarrystone or specially shaped concrete armor units.
- 2. Previous investigations under Work Unit No. 31269, "Stability of Breakwaters," have yielded a significant quantity of design information for new construction using quarrystone (Hudson 1958 and Carver 1980, 1983), tetrapods, quadripods, tribars, modified cubes, hexapods, and modified tetrahedrons (Jackson 1968), dolosse (Carver and Davidson 1977 and Carver 1983), and toskane (Headquarters, US Army Corps of Engineers 1978). Rehabilitation projects on several of the Corps' rubble-mound structures have revealed a total lack of design guidance or even information concerning the interfacing and stability response of armor units that are of dissimilar type and/or size. In the past, selection of new armor type, method of interfacing, and procedures for preparation of the existing section have been based on engineering judgment or, more recently, on site-specific model studies. The engineering judgment process may be expensive since experience is limited and a solid basis seldom exists. This process can lead to recurring failures that cost millions of dollars without developing a real solution to the long-term problem. Sitespecific model studies have provided good singular solutions, but sitespecific data usually fail to meet the requirements of other projects (Carver 1988). It is anticipated that the problem will become more acute in future years as rehabilitation of major breakwaters and jetties becomes necessary to extend their project life or to meet greater design demands.

Approach

3. Model breakwaters and armor units are used to experimentally investigate the stability response of various armor combinations for selected structure geometries and wave conditions. It would be an extremely extensive task to comprehensively investigate all different types of existing armor units; therefore, this research effort will address only the three types (stone, dolos, and tribars) of armor most commonly used in the Corps. Selection of these armor types should give test results the widest range of applicability possible. Tests will be conducted with breaking wave conditions on no-damage, no-overtopping breakwater trunk and head sections by using sea-side slopes of 1V on 1.5H and 1V on 2H.

Purpose of Study

4. The purpose of the present investigation was to obtain design guidance for dolos and tribar overlays used to rehabilitate stone-armored rubble-mound breakwater and jetty trunks subjected to breaking waves. More specifically, it was desired to determine the minimum weight of individual armor units (with given specific weights) required for stability as a function of the type of armor unit, sea-side slope of the structure, wave period, wave height, and water depth.

PART II: TESTS

Stability Scale Effects

5. If the absolute sizes of experimental breakwater materials and wave dimensions become too small, flow around the armor units enters the laminar regime; and the induced drag forces become a direct function of the Reynolds number. Under these circumstances prototype phenomena are not properly simulated, and stability scale effects are induced. Hudson (1975) presents a detailed discussion of the design requirements necessary to ensure the preclusion of stability scale effects in small-scale breakwater tests and concludes that scale effects will be negligible if the Reynolds stability number $(R_N)^*$

$$R_{N} = \frac{g^{1/2}H^{1/2}l_{a}}{v}$$

where

 $g = acceleration due to gravity, ft/sec^2$

H = wave height, ft

 ℓ_{a} = characteristic length of armor unit, ft

v = kinematic viscosity

is equal to or greater than 3×10^4 . For all tests reported herein, the sizes of experimental armor and wave dimensions were selected such that scale effects were insignificant (i.e., R_N was greater than 3×10^4).

Test Procedures

Method of constructing test sections

6. All experimental breakwater sections were constructed to reproduce as closely as possible results of the usual methods of constructing full-scale breakwaters. The core material was dampened as it was dumped by bucket or shovel into the flume and was compacted with hand trowels to simulate natural consolidation resulting from wave action during construction of the prototype

^{*} Symbols are identified in Appendix A.

structure. Once the core material was in place, it was sprayed with a low-velocity water hose to ensure adequate compaction of the material. The underlayer stone was then added by shovel and smoothed to grade by hand or with trowels. No excessive pressure or compaction was applied during placement of the underlayer stone. Armor units used in the cover layers were placed in a random manner corresponding to work performed by a general coastal contractor; i.e., they were individually placed but were laid down without special orientation or fitting. After each test series the armor units were removed from the breakwater, all of the underlayer stones were replaced to the grade of the original test section, and the armor was replaced.

Selection of critically breaking waves

- 7. For the given wave period and water depth, the most detrimental breaking wave (i.e., the most damaging wave) was determined by increasing the stroke adjustment on the wave generator in small increments and observing which wave produced the most severe breaking wave condition on the experimental structures. Wave heights of lower amplitude did not form the critical breaking wave and wave heights of larger amplitude would break seaward of the test structures and dissipate their energy so that they were less damaging than the critically tuned wave.
- 8. A typical stability test series consisted of subjecting the test sections to attack by waves of given heights and periods until all damage had abated or the structures failed. Test sections were subjected to wave attack in approximately 30-sec intervals between which the wave generator was stopped and the waves were allowed to decay to zero height. This procedure was necessary to prevent the structures from being subjected to an undefined wave system created by reflections from the experimental breakwater and wave generator. Newly built test sections were subjected to a short duration (five or six 30-sec intervals) of shakedown by using a wave equal in height to about one-half of the design wave. This procedure provided a means of allowing consolidation and armor unit seating that would normally occur during prototype construction.

Method of determining damage

9. In order to evaluate and compare breakwater stability test results, it is necessary to quantify the changes that have taken place in a given structure during attack by waves of specified characteristics. The US Army Engineer Waterways Experiment Station (WES) developed a method of measuring

the percent damage incurred by a test section during the early 1950's. This method has proven satisfactory and was used as a means for analyzing and comparing the stability tests delineated within this report.

10. The WES damage-measurement technique requires that the cross-sectional area occupied by armor units be determined for each stability test section. Armor unit area is computed from elevations (soundings) taken at closely spaced grid-point locations before the armor is placed on the underlayer, after the armor has been placed but before the section has been subjected to wave attack, and finally after wave attack. Elevations are obtained with a sounding rod equipped with a circular spirit level for plumbing, a scale graduated in thousandths of a foot, and a ball-and-socket foot for adjustment to the irregular surface of the breakwater slope. The diameter (Diam) in inches of the circular foot of the sounding rod was related to the size of the material being sounded by the following equation:

$$Diam = C \left(\frac{W_a}{\gamma_a}\right)^{1/3} \tag{1}$$

where

C = coefficient

W = weight of an armor unit, 1b

 γ_a = specific weight of armor unit, pcf

C = 6.8 for tribars and stone and 13.7 for dolosse. A series of sounding tests in which both the weight of the armor and the diameter of the sounding foot were varied indicated that the above relation would give a measured thickness which visually appeared to represent an acceptable two-layer thickness.

11. Sounding data for each test section were obtained as follows: after the underlayer was in place, soundings were taken on the slopes of the structure along rows beginning at and parallel to the longitudinal center line of the structure and extending in 0.25-ft horizontal increments until the edge of the armor was reached. On each parallel row, sounding points, spaced at 0.25-ft increments, were measured. The 0.5 ft of structure next to each wall was not considered because of the possibility of discontinuity effects between armor units and the flume walls. Soundings were taken at the same points once

^{*} A table of factors for converting non-SI units of measurement to SI (metric) units is presented on page 3.

the armor was in place and again after the structure had been subjected to wave attack.

12. Sounding data from each stability test were reduced in the following manner. The individual sounding points obtained on each parallel row were averaged to yield an average elevation at the bottom of the armor layer before the armor was placed and then at the top of the armor layer before and after testing. From these values, the cross-sectional armor area before testing and the area from which armor units were displaced (either downslope or off the section) were calculated. Damage was then determined from the following relation:

Percent damage =
$$\frac{A_2}{A_1}$$
 (100) (2)

where

 A_2 = area from which armor units have been displaced, ft² A_1 = area before testing, ft²

The percentage given by the WES sounding technique is, therefore, a measurement of an end area which converts to an average volume of armor material that has been moved from its original location (either downslope or off-structure).


Test Equipment

13. All tests were conducted in a 5-ft-wide, 4-ft-deep, 119-ft-long concrete wave flume with test sections installed about 90 ft from a vertical displacement wave generator. A thin divider was installed in the center of the test section area, thus yielding two 2.5-ft-wide sections. The first 10-ft length of flume bottom, immediately seaward of the test sections, was molded on a IV-on-10H slope while the remaining 80-ft length was flat. The generator is capable of producing sinusoidal waves of various periods and heights. For all tests, waves of the required characteristics were generated by varying the frequency and amplitude of the plunger motion. Changes in water-surface elevation as a function of time (wave heights) were measured by electrical wave-height gages in the vicinity of where the toe of the test sections was to be placed (without the structure in place) and recorded on

chart paper by an electrically operated oscillograph. The electrical output of the wave gages was directly proportional to their submergence depth.

Selection of Test Conditions

- 14. Breaking wave tests were conducted using both tribar and dolos armor overlays. A review of past site-specific stability projects and hydrographic data showed that typical prototype sea-bottom slopes could range from almost flat to as steep as 1V on 10H. Severity of breaking action increases as bottom slope increases and since time restraints would allow testing of only one foreslope, it was decided to use a 1V-on-10H slope, thus ensuring severe depth-limited breaking wave action (plunging breakers). When breaking directly on the structure, this type of wave normally causes the most damage to rubble-mound structures.
- 15. By nondimensionalizing design conditions from site-specific projects, it was found that a relative depth (d/L) range of 0.04 to 0.14 should include most prototype conditions encountered in breaking-wave stability designs. A review of capabilities of the available flume and wave generator showed that this range of d/L values could be achieved for a reasonable range of testing depths.
- 16. The wave flume was calibrated for depths from 0.40 to 0.95 ft in 0.05-ft increments at d/L values of 0.04, 0.06, 0.08, 0.10, 0.12, and 0.14. This range of depths, and consequently breaking wave heights, proved to be compatible with the selected armor weights and sea-side breakwater slopes.
- 17. All stability tests were conducted on sections of the type shown in Figure 1 and Photos 1-3. Sea-side slopes of 1V on 1.5H and 1V on 2H were investigated while the beach-side slope was held constant at 1V on 1.5H. Heights of the simulated existing structures (prior to placement of the dolos or tribar overlays) varied from 1.0 to 1.4 ft. The height necessary to prevent wave overtopping of the existing structure was determined from slopes and estimated water depths and wave heights to be investigated in determining stability coefficients $(K_D^{\dagger}s)$ for the dissimilar armor overlays.
- 18. It was assumed that the existing armor stone was only marginally stable and the dolos and tribar overlays would have $\rm K_{0}$ equal to those obtained in new construction. Based on these assumptions, the stable tribar weights would be approximately equal to the weight of the existing armor stone



WEIGHT, LB	0.55	0.627	0.276	0.589	
ARMOR TYPE	EXISTING STONE	TRIBAR OVERLAY	DOLOS OVERLAY	DOLOS OVERLAY	

Figure 1. Typical breakwater cross section

and the dolos weights would vary from one-half up to the armor stone weight, depending on the degree of conservatism used in their selection. A review of existing model materials was made in concert with these assumptions and a 0.55-1b stone was selected to simulate existing conditions. Tests were conducted using 0.627-1b tribar overlays and 0.276- and 0.589-1b dolos overlays.

PART III: TEST RESULTS

Sea-Side Structure Slope = 1V on 2H

19. Stability test results for dolos and tribar overlays constructed on a 1V-on-2H slope are summarized in Table 1. Presented herein are experimentally determined $K_D^{\dagger}s$ as functions of d/L and relative wave height (H/d). The stability coefficient, $K_D^{}$, is determined from the Hudson formula, i.e.,

$$W_{a} = \frac{\gamma_{a}H^{3}}{K_{D}(S_{a} - 1)^{3} \cot \alpha}$$

where

 K_{D} = stability coefficient

 $S_a = \text{specific gravity of armor unit}$

 α = reciprocal of breakwater slope

Armor units were placed randomly in two layers and the number of armor units per given surface area was equal to that presently recommended for new construction in EM 1110-2-2904, "Design of Breakwaters and Jetties" (Headquarters, Department of the Army 1986). Photos 4-10 show typical after-testing conditions of structures.

20. Figures 2 and 3 present $K_{\overline{D}}$ as a function of d/L and H/d, respectively. These data show dolos stability to be sensitive to both d/L and H/d with minimum stability occurring at the lower values of d/L and higher values of H/d, i.e., longer wave periods in shallower water. These trends are consistent with those observed by Carver (1983) for dolos used in new construction. Influences of H/d and d/L on tribar stability do not appear to be significant in the present data. The minimum $K_{\overline{D}}$ observed for tribars is equal to that obtained for new construction and to that observed for dolos is about 15 percent less (12.8 versus 15).

Sea-Side Structure Slope = 1V on 1.5H

21. Stability tests were initiated at the 1V-on-1.5H slope using dolos armor units randomly placed in two layers. Results of these tests, summarized




Figure 2. Stability coefficient $\rm K_{\mbox{\scriptsize D}}$ versus relative depth $\rm \,d/L$ $\rm \,cot~\alpha$ = 2.0




Figure 3. Stability coefficient $\rm K_{\sc D}$ versus relative wave height H/d cot α = 2.0

in Table 2 and depicted in Photos 11-14, were similar to those obtained at the 1V-on-2H slope. However, a slight decrease in stability was observed.

- 22. Tribar tests were initiated with two layers of randomly placed units and an assumed $\rm K_D$ of 9. This structure proved to be unstable. Wave heights were progressively reduced to 0.33 ft without achieving stability. Generally, the tribars did not interface well with the larger armor stone at this steeper slope and were prone to downslope shifting. Photos 15 and 16 show the structure after attack of 0.38- and 0.33-ft waves, respectively. If stability had been achieved, the corresponding $\rm K_D^1s$ would be 4.2 and 2.7. Based on these test results, randomly placed tribars are not recommended for overlaying existing armor stone at slopes steeper than 1V on 2H.
- 23. Random tribar placement was tested initially because this type is generally the most economical and reliable to construct in the field. However, one layer of uniform tribar placement in concert with large toe buttressing stone has been used by Pacific Ocean Division (POD). Therefore, it was decided to investigate the stability of this configuration. Based on POD's experience, a buttressing stone weight about 1.3 times greater than the tribar weight was selected. Photo 17 shows the structure before wave attack and Photos 18 and 19 show typical after-testing views.
- 24. Results of stability tests for the uniformly placed tribars are summarized in Table 2 along with the previously discussed dolos test results. These data indicate a minimum stability coefficient of 7.0 for the uniformly placed tribars. Figures 4 and 5 present $\rm K_D$ as a function of d/L and H/d , respectively. Similar to results for the lV-on-2H slope, dolos stability proved to be sensitive to d/L and H/d with minimum stability occurring at the lower values of d/L and higher values of H/d and tribar stability was not significantly influenced by either d/L or H/d .
- 25. Minor rocking and shifting of the buttressing stone was observed during some of the tests; therefore, the selected weight (1.3 tribar weights) is recommended as a true minimum. Also, stability results achieved for the uniformly placed tribars are highly dependent on the careful placement of the tribars in concert with the buttressing stone. Specifications should clearly state that gaps between the units are not acceptable as voids invite downslope slippage and may lead to failure of the overlay.




Figure 4. Stability coefficient $K_{\mbox{\scriptsize D}}$ versus relative depth d/L cot α = 1.5




Figure 5. Stability coefficient $K_{\rm D}$ versus relative wave height H/d cot α = 1.5

PART IV: CONCLUSIONS

- 26. Based on tests and results described herein in which dolos and tribar armor are used to overlay existing armor stone on breakwater trunks and subjected to breaking waves with a direction of approach of 90 deg, it is concluded that:
 - <u>a.</u> Randomly placed dolos are an acceptable option, provided that a stability coefficient of 12 is used to size the units.
 - b. Dolos stability proved to be sensitive to d/L and H/d with minimum stability occurring at the lower values of d/L and higher values of H/d , i.e., longer wave periods in shallower water.
 - c. Randomly placed tribars are not recommended at slopes steeper than 1V on 2H; however, they may be used at milder slopes with a stability coefficient of 9.
 - d. Uniformly placed tribars are an acceptable option for a 1V-on-1.5H slope provided that they are used in concert with the buttressing stone, size selection is based on a stability coefficient of 7, and placement of the units replicates that used in the model.
 - \underline{e} . Tribar stability appears to be insensitive to d/L and H/d for both types of placement.

REFERENCES

- Carver, R. D. 1980 (Jan). "Effects of First Underlayer Weight on the Stability of Stone-Armored Rubble-Mound Breakwater Trunks Subjected to Nonbreaking Waves with No Overtopping; Hydraulic Model Investigation," Technical Report HL-80-1, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- . 1983 (Dec). "Stability of Stone- and Dolos-Armored, Rubble-Mound Breakwater Trunks Subjected to Breaking Waves With No Overtopping," Technical Report CERC-83-5, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- . 1988. "Prototype Experience with the Use of Dissimilar Armor for Repair and Rehabilitation of Rubble-Mound Coastal Structures," Technical Report REMR-CO-2, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- Carver, R. D., and Davidson, D. D. 1977 (Nov). "Dolos Armor Units Used on Rubble-Mound Breakwater Trunks Subjected to Nonbreaking Waves with No Overtopping," Technical Report H-77-19, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- Headquarters, Department of the Army. 1986 (Aug). "Engineering and Design; Design of Breakwaters and Jetties," EM 1110-2-2904, Washington, DC
- Headquarters, US Army Corps of Engineers. 1978. "Hydraulic Model Tests of Toskane Armor Units," Engineer Technical Letter ETL 1110-2-233, Washington, DC.
- Hudson, R. Y. 1958 (Jul). "Design of Quarry-Stone Cover Layers for Rubble-Mound Breakwaters; Hydraulic Laboratory Investigation," Research Report No. 2-2, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- . 1975 (Jun). "Reliability of Rubble-Mound Breakwater Stability Models; Hydraulic Model Investigation," Miscellaneous Paper H-75-5, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.
- Jackson, R. A. 1968 (Jun). "Design of Cover Layers for Rubble-Mound Breakwaters Subjected to Nonbreaking Waves; Hydraulic Laboratory Investigation," Research Report No. 2-11, US Army Engineer Waterways Experiment Station, Vicksburg, Miss.

Table 1 Values of H , d/L , H/d , and K $_{\overline{D}}$ for Dolos and Tribar Armor

Overlays of Existing Stone Armor When Subjected to Breaking Waves; 1V-on-2H Structure Slope

W _a , 1b	d , ft	T , sec	H , ft	d/L	H/d	KD
		Dol	os Armor			
0.276	0.55	1.70	0.54	0.08	0.98	19.5
0.276	0.95	1.37	0.61	0.14	0.66	27.9
0.589	0.65	1.85	0.60	0.08	0.92	12.8
0.589	0.70	1.57	0.63	0.10	0.90	14.9
0.589	0.85	1.73	0.71	0.10	0.84	21.4
0.589	0.90	1.78	0.77	0.10	0.86	27.2
		Trib	ar Armor			
0.627	0.55	1.70	0.54	0.08	0.98	9.0
0.627	0.60	2.32	0.58	0.06	0.97	11.2
0.627	0.70	1.34	0.55	0.12	0.79	9.5
0.627	0.85	1.30	0.56	0.14	0.66	10.1

Waves; 1V-on-1.5H Structure Slope

, 1b KD H , ft d/LH/d d , ft T , sec Dolos Armor 0.276 0.40 2.82 0.42 0.04 1.05 12.1 0.276 0.45 2.02 0.46 0.06 1.02 15.9 0.276 0.50 1.32 0.42 0.10 0.84 12.1 0.51 0.12 0.78 21.8 0.276 0.65 1.29 0.98 12.5 1.70 0.54 0.08 0.589 0.55 0.589 0.60 2.32 0.58 0.06 0.97 15.6 0.589 0.95 1.37 0.61 0.14 0.64 18.0 Tribar Armor 0.06 1.02 7.4 0.627 0.45 2.02 0.46 0.10 0.82 7.0 0.627 0.55 1.39 0.45 1.24 0.45 0.12 0.75 7.0 0.627 0.60

0.46

0.14

0.71

7.4

0.627

0.65

1.13




Photo 1. End view of a typical dolos section before wave attack at a 1V-on-2H sea-side structure slope; W_a = 0.276 lb




Photo 2. Sea-side view of a typical dolos section before wave attack at a 1V-on-2H sea-side structure slope; W_a = 0.276 1b




Photo 3. End view of a typical tribar section before wave attack at a 1V-on-2H sea-side structure slope; $\rm W_a$ = 0.627 lb




Photo 4. Sea-side view after attack of 1.70-sec, 0.54-ft waves; d = 0.55 ft; $W_a = 0.276$ lb; 1V-on-2H structure slope; dolos armor



Photo 5. Sea-side view after attack of 1.37-sec, 0.61-ft waves; d = 0.95 ft; $W_a = 0.276$ lb; lV-on-2H structure slope; dolos armor




Photo 6. Sea-side view after attack of 1.85-sec, 0.60-ft waves; d = 0.65 ft; W_a = 0.589 lb; lV-on-2H structure slope; dolos armor




Photo 7. End view after attack of 1.73-sec, 0.71-ft waves; d = 0.85 ft; W_a = 0.589 lb; lV-on-2H structure slope; dolos armor




Photo 8. End view after attack of 1.78-sec, 0.77-ft waves; d = 0.90 ft; W_a = 0.589 lb; lV-on-2H structure slope; dolos armor



Photo 9. End view after attack of 2.32-sec, 0.58-ft waves; d = 0.60 ft; $W_a = 0.627$ lb; IV-on-2H structure slope; tribar armor



Photo 10. End view after attack of 1.30-sec, 0.56-ft waves; d = 0.85 ft; W_a = 0.627 lb; lV-on-2H structure slope; tribar armor




Photo 11. Sea-side view after attack of 2.82-sec, 0.42-ft waves; d = 0.40 ft; W_a = 0.276 lb; lV-on-1.5H structure slope; dolos armor



Photo 12. Sea-side view after attack of 1.29-sec, 0.51-ft waves; d = 0.65 ft; W_a = 0.276 lb; lV-on-1.5H structure slope; dolos armor




Photo 13. Sea-side view after attack of 1.70-sec, 0.54-ft waves; d = 0.55 ft; $W_a = 0.589$ 1b; 1V-on-1.5H structure slope; dolos armor



Photo 14. End view after attack of 1.37-sec, 0.61-ft waves; d = 0.95 ft; W_a = 0.589 lb; lV-on-1.5H structure slope; dolos armor



Photo 15. Sea-side view after attack of 1.18-sec, 0.38-ft waves; d = 0.55 ft; $W_a = 0.627$ lb; $W_$



Photo 16. End view after attack of 1.07-sec, 0.33-ft waves; d = 0.45 ft; $W_a = 0.627$ lb; 1V-on-1.5H structure slope; tribar armor



Photo 17. Sea-side view of uniformly placed tribar armor before wave attack at a 1V-on-1.5H structure slope



Photo 18. Sea-side view after attack of 2.02-sec, 0.46-ft waves; d = 0.45 ft; W_a = 0.627 lb; lV-on-1.5H structure slope; uniformly placed tribars




Photo 19. Sea-side view after attack of 1.13-sec, 0.46-ft waves; d = 0.65 ft; W_a = 0.627 lb; 1V-on-1.5H structure slope; uniformly placed tribars

APPENDIX A: NOTATION

Surface area, ft² A, and A2 С Coefficient Water depth, ft đ Relative depth d/L Acceleration due to gravity, ft/sec² g Wave height, ft Н H/d Relative wave height Stability coefficient K_{D} Characteristic length of armor unit, ft la Reynolds stability number = $g^{1/2}H^{1/2}\ell_{\nu}$ R_N Specific gravity of armor unit relative to water in which it is placed Т Wave period sec, time Weight of an armor unit, 1b Reciprocal of breakwater slope Specific weight of armor unit, pcf γ_a Kinematic viscosity





